





# Photometric Measurements

Photometrische Messungen | Mesures Photométriques  
Mediciones Fotométricas


## TS 100 WW (CLTS100WW)




## Television Lighting Consistency Index-2012

CCT = P3007 (-0,0)



TLCI-2012: 97 (P3007)



Sector	Lightness	Chroma	Hue
R	0	0	0
R/Y	0	0	0
Y	0	0	0
Y/G	0	0	0
G/C	0	0	0
C	0	0	0
C/B	0	0	-
B	0	0	0
B/M	0	0	+
M	+	+	0
M/R	+	0	0



## TM-30-15 $R_f$ 91 $R_g$ 98 $R_f$ - $R_g$ Plot



● Cameo TS-100